(SRI KADIDAL MANJAPPA.)

(*b*) The matter is still under investigation.

ಶ್ರೀ ಯು. ಎಂ. ಮಾದಪ್ಪ.—"ಚಾಲ್ತಿ ಸಾಲಿನ ಬಡ್ಜೆಟ್ಟಿನಲ್ಲಿ ಯಾವ ಮೊಬಲಗನ್ನೂ ಒದಗಿಸಿಲ್ಲ" ಎಂದು ಉತ್ತರದಲ್ಲಿ ಹೇಳಿದೆ. ಆದರೆ 1953-54ನೆಯ ಸಾಲಿನ ಬಡ್ಜೆಟ್ ಎಸ್ಟಿಮೇಟಿನ 336ನೆಯ ಪುಟದಲ್ಲಿರುವ ಅಪೆಂಡಿಕ್ಸ್ (c) ನಲ್ಲಿ ಹತ್ತು ಸಾವಿರ ರೂಪಾಯಿಗಳನ್ನು ಒದಗಿಸಿರುವುದು ಸರ್ಕಾರದ ಗಮನದಲ್ಲಿದೆಯೆ ?

Sri KADIDAL MANJAPPA.—I will examine it, Sir.

---

*Attigere Tank in Mulbagal Taluk.*

*Q.*—106. Sri G. NARAYANA GOWDA (Mulbagal-Srinivasapur).—

Will the Government be pleased to state :—

(*a*) when the major tank (Attikere) belonging to Upparahalli and Byatanur of Byrakur Hobli in Mulbagal Taluk breached ;

(*b*) whether there were representations for the restoration of the same ;

(*c*) the steps the Government have taken in this regard ?

*A.*—Sri KADIDAL MANJAPPA (Minister for Revenue and Public Works).—

(*a*) About 50 years back.

(*b*) Yes.

(*c*) During the year 1942 an estimate for the restoration of this tank was got up for Rs. 7,200. As the Madras Government objected to the restoration, it was allowed to lie over.

ಶ್ರೀ ಜಿ. ನಾರಾಯಣಗೌಡ.—(*c*) ಪ್ರಶ್ನೆಗೆ ಉತ್ತರವಾಗಿ "ಜೀರ್ಣೋದ್ಧಾರದ ವಿಷಯವನ್ನು ಹಾಗೆಯೇ ಬಿಟ್ಟುಬಿಡಲಾಯಿತು" ಎಂದು ಹೇಳಿದೆ. ಯಾವ ಆಧಾರದ ಮೇಲೆ ಹಾಗೆ ಮಾಡಲಾಯಿತು ?

ಶ್ರೀ ಕಡಿದಾಳ್ ಮಂಜಪ್ಪ.—1942ನೆಯ ಇಸವಿಯಲ್ಲಿ ನಮಗೂ ಅವರಿಗೂ ಆಗಿರುವ ಒಪ್ಪಂದದ ಪ್ರಕಾರ.

ಶ್ರೀ ಜಿ. ನಾರಾಯಣಗೌಡ.—ಈ ಒಪ್ಪಂದ ಕೆರೆ ಒಡೆದುಹೋಗಿರುವುದಕ್ಕೆ ಅನ್ವಯವಾಗುತ್ತದೆಯೋ ಅಥವಾ ಹೊಸದಾಗಿ ಕಟ್ಟುವುದಕ್ಕೆ ಅನ್ವಯಿಸುತ್ತದೆಯೋ ?

ಶ್ರೀ ಕಡಿದಾಳ್ ಮಂಜಪ್ಪ.—ಇದನ್ನು ಪರಿಶೀಲಿಸುತ್ತೇವೆ.

---

*Repair of breached tanks in Chikmagalur District.*

*Q.*—175. Srimathi B. L. SUBBAMMA (Chikmagalur—Mudigere).—

Will the Government be pleased to state :—

(*a*) the number of tanks breached in the Chikmagalur District during the last rainy season (talukwar details to be furnished) ;

(*b*) the steps taken by them in this behalf ?

*A.*—Sri KADIDAL MANJAPPA (Minister for Revenue and Public Works).—

(*a*) Four tanks. Statement appended below.

(*b*) Measures have been taken to repair the damage by completing urgent works as indicated in the Annexure to clause (*a*).

Statement showing the breached tanks in Chikmagalur District during the last rainy season talukwar.

| *Name of Tank* | *Remarks* |
|---|---|
| 1. Chikmagalur Taluk.— | |
| Belavadi Doddakere Register No. 1320. | Ring bund to stores 2 feet of water is completed and traffic restored. Main breach filling is in progress. |
| 2. Kadur Taluk.— | |
| Ganganahalli tank Register No. 720. | Estimate is prepared and is pending irrigation enquiry as per new Irrigation Act. |
| 3. Tarikere Taluk.— | |
| Yelevegere Agasarakatte Register No. 138. | Work completed. |
| 4. Narsimharajapura Taluk.— | |
| Vittala Thotadakere Register No. 183. | Work completed. |